## LAKE MACQUARIE AIRPORT
## ELEV 5
## AVFAX CODE 2090
## FULL NOTAM SERVICE NOT AVBL

NSW UTC +10 YLMQ
330358S 1513853E VAR 12 DEG E UNCR
AD OPR Lake Macquarie Airport Pty Ltd, PO Box 988, Warners Bay, NSW, 2282. Email: contact@lakemacquarieairport.com.au. PH ARO 02 4944 9199 or 0408 449 198. Website: www.lakemacquarieairport.com.au.

### REMARKS
1. PPR in writing to ARO.
2. Rescue HEL Service EMERG OPS take precedence. Response time 10MIN.
3. Airfield status subject to change without notice.
4. AD Charges and landing fee apply.

### PHYSICAL CHARACTERISTICS
07/25 27c Unrated. Central 11 sealed. WID 18 RWS 90
Length 880M.
Displaced thresholds for landing due to possible obstructions - PPR.

### OTHER LIGHTING
Runway lighting not available.

### ATS AND AERODROME COMMUNICATION FACILITIES
FIA BRISBANE CENTRE 125.7 On ground

### LOCAL TRAFFIC REGULATIONS
Carriage and use of radio is required by AD OPR.

**CTAF** 132.1

### NOISE ABATEMENT PROCEDURES
1. Noise sensitive area.
2. All ACFT required to be familiar with YLMQ procedure document on website.
3. Avoid all built up areas.
4. Avoid golf course to east.
5. No flight below 1,000FT AMSL.

### ADDITIONAL INFORMATION
1. HEL OPS.
2. Frequent EMERG service OPS.
3. Microlight and gyrocopters operate from this AD. Gyrocopters may occupy RWY for longer than normal due to building up rotor speed.
4. PJE occur HJ on airfield from FL150, Pilots advised to monitor CTAF and BN CEN for DZ status.
5. Refer to YLMQ Westpac Rescue Helicopter for Helicopter Emergency Medical Service OPS.

### CHARTS RELATED TO THE AERODROME
1. WAC 3456.
2. Also refer AIP Departure and Approach Procedures.

Information may be continued on the next page: PTO