


**MARYBOROUGH (VIC)****ELEV 766****FULL NOTAM SERVICE NOT AVBL**

VIC  
370159S 1434232E UTC +10 YMBU  
VAR 11 DEG E UNCR

AD OPR Central Goldfields Shire Council, 22 Nolan Street, Maryborough,  
3465. Email: mail@cgoldshire.vic.gov.au. PH 03 5461 0610. Fax 03 5461  
0666.

**REMARKS**

AD not AVBL to ACFT ABV 5,700KG MTOW.

**PASSENGER FACILITIES**

WC/TX (03 5461 1633)/RF/LG (Access Code C1191)

**AERODROME OBSTACLES**

Trees in the vicinity of runway may impact the approach or departure of  
aircraft.

**PHYSICAL CHARACTERISTICS**

|       |       |                              |        |        |
|-------|-------|------------------------------|--------|--------|
| 06/24 | 21    | PCN 6 /F /C /5700/ /U Gravel | WID 30 | RWS 90 |
| 17/35 | 34a/b | PCN 6 /F /C /5700/ /U Sealed | WID 30 | RWS 90 |

**AERODROME AND APPROACH LIGHTING**

RWY 17/35 LIRL AFRU+PAL 119.1

RWY edge light spacing: 17/35: 87M.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA MELBOURNE CENTRE 126.8 Circuit Area

**LOCAL TRAFFIC REGULATIONS**

1. Circuit training not permitted 2200-0700 Local.
2. ACFT on different RWY may not be visible to each other.
3. HLS FATO/TKOF 35M diameter. HLS MTOW unlimited.
4. Radios to be carried and used.

**FLIGHT PROCEDURES**

Right hand circuit RQ when OPR on RWY 17 and 24.

**CTAF - AFRU 119.1**

**ADDITIONAL INFORMATION**

1. Bird hazard exists.
2. Kangaroos may be on RWY - pilots should conduct a flyover before landing.

**CHARTS RELATED TO THE AERODROME**

WAC 3469.