ELEV 1312

MILLMERRAN

218° 0.43NM Millmerran

OI D 275148S

FULL NOTAM SERVICE NOT AVBL UTC +10 YMMN 1511630E VAR 11 DEG E UNCR AD OPR Toowoomba Regional Council, PO Box 3021, Toowoomba, QLD, 4350,

Email: aerodrome@tr.gld.gov.au. PH BH Aerodrome 07 4688 6117. Council PH AH 0497 099 111. Website: www.tr.gld.gov.au/aerodromes.

REMARKS

- Current AD charges. See website. 1.
- 2. ACFT BLW 2.000KG day use only.
- Pavement concession required for larger ACFT. Contact AD OPR. 3.
- 4. Access AVBL in accordance with Toowoomba Region Aerodromes Conditions of Access and Use. See website.
- 5. Due to safety/security hazards, ensure vehicle gates are closed and locked when not in use.

PASSENGER FACILITIES

LG/WC.

APRONS AND TAXIWAYS

- TWY to APN and hangar area. 1.
- 2. GA APN.

AERODROME OBSTACLES

- Transitional OLS tree infringement exists up to 24FT left and right of APCH to SE THR 31 1. end.
- 2. Unlit primary wind indicator located BTN RWS and apron infringes transition OLS by 10FT (based on a 60M wide RWS).

PHYSICAL CHARACTERISTICS

13/31 40a/c 2000/600 (87PSI) Unrated. Grass. Central 11M WID 18 **RWS 80** sealed, RWY LEN 1.230M.

Caution: outer 2M each side of sealed central runway section may be soft due to sub-surface moisture, particularly during wet weather. Central 6M are firm and stable.

ATS AND AERODROME COMMUNICATION FACILITIES 121.2 500FT

FIA **BRISBANE CENTRE**

CTAF 126.7

ADDITIONAL INFORMATION

- 1. Assume that bird and animal hazard exists. Arriving ACFT should conduct aerial RWY inspection prior to landing.
- 2. Tyre pressure is in accordance with AIP unrated pavements.
- 3. Unsealed areas not suitable in wet weather or after rain.
- Qantas Group Pilot Academy operates from YBWW. CAUTION: increased flight training 4. traffic YMMN circuit and adjacent areas extending to Leyburn, Millmerran and Cecil Plains.
- CAUTION: Mining operations (blasting possible) BRG 176 MAG APRX 8KM FM AD. 5.

CHARTS RELATED TO THE AERODROME

WAC 3340.