SERPENTINE

FLEV 30 FULL NOTAM SERVICE NOT AVBL



PPR.

WA **UTC +8** YSEN 322342S 1155224E VAR 2 DEG W UNCR AD OPR Sport Aircraft Builder's Club of WA Inc. Yangedi Road North. Hopeland, WA, 6125, Email: secretary@sabc.org.au, PH Club House 08

9525 2085 (not always manned). Website: www.sabc.org.au. REMARKS

1.

2.

Helicopter OPS 24/7.

AERODROME OBSTACLES

High voltage powerlines intersects APCH slope 500M to West of THR 05. 1

2. Trees to 10M short final 27.

PHYSICAL CHARACTERISTICS

WID 12 Unrated, Sealed, RWY LEN 900M, RWY 23 05/23 30a **RWS 15** DTHR 100M. Unrated, Grass, RWY LEN 600M. **WID 24** 09/27 20c **RWS 30**

AERODROME AND APPROACH LIGHTING

RWY 05/23 MIRI PAL 125.3 RWY 05/23 edge LGT spacing: 96M.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA PERTH CENTRE

135.25 On ground

LOCAL TRAFFIC REGULATIONS

ACFT should manoeuvre on TWY and RWY only due to soft sand.

FLIGHT PROCEDURES

- RWY 05 MNM CCT HGT 1,000FT. 1.
- 2. CCTS not permitted before 0800 on SUN.

CTAF 119.1

ADDITIONAL INFORMATION

- 1. RWY 09/27 grass RWY sprinklers may be operating during summer months.
- 2. Murray Field AD has identical RWY numbers and CTAF.
- 3. Kangaroo and bird hazard exists all areas.
- Low level aerobatics in VCY. 4.
- Perth VTC and VNC. 5.

CHARTS RELATED TO THE AERODROME

WAC 3462.