


**TANAMI****ELEV 1400****FULL NOTAM SERVICE NOT AVBL**

NT  
195800S                      1294332E                      UTC +9:30                      YTMN  
VAR 3 DEG E                      UNCR

AD OPR Northern Star (Tanami) Pty Ltd, Level 1/388 Hay Street, Subiaco, WA, 6008. Email: TanamiAdmin@nsr ltd.com. PH 08 6211 2650.

**REMARKS**

PPR - Contact AD OPR

**AERODROME OBSTACLES**

1. RWY 12 APCH surface infringed - stockpile 445M prior to THR 41F ABV inner edge.
2. RWY 30 stockpile 2,174M FM SOT 61.4M L of EXT CL 62FT ABV RWY gradient 2.91%.
3. RWY 30 stockpile 2,209M FM SOT 13.1M R of EXT CL 63FT ABV RWY gradient 2.79%.
4. Refer AD OPR for OBST chart.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA                      BRISBANE CENTRE                      118.9 6500FT  
UNICOM                      TANAMI UNICOM                      128.9 (1)  
(1)                      CS "Tanami Mine".

**LOCAL TRAFFIC REGULATIONS**

1. Initial contact is on UNICOM 128.9 to Tanami Ground then change to CTAF 126.7.
2. Preferred night OPS - land RWY 30, TKOF RWY 12.

**CTAF** 126.7

**ADDITIONAL INFORMATION**

Night OPS for emergencies only i.e. RFDS - land RWY30, TKOF RWY 12

**CHARTS RELATED TO THE AERODROME**

WAC 3222.