

SERPENTINE**ELEV 30****FULL NOTAM SERVICE NOT AVBL**

WA

UTC +8

YSEN


322342S

1155224E

VAR 2 DEG W

UNCR

AD OPR Sport Aircraft Builder's Club of WA Inc, Yangedi Road North,
Hopeland, WA, 6125. Email: secretary@sabc.org.au. Website:
www.sabc.org.au.

**REMARKS**PPR. Email request for permission to committee@sabc.org.au.**HANDLING SERVICES AND FACILITIES**

PPR to confirm fuel AVBL. AVGAS and MOGAS 95 AVBL H24. Accepts Dunning Card and credit card (V and MC). Other cards not accepted. For system faults: PH 0407 199 681.

AERODROME OBSTACLES

1. High voltage powerlines running North to South 900M West of AD boundary.
2. Trees to 10M short final RWY 27.

PHYSICAL CHARACTERISTICS

05/23 30a Unrated. Sealed. RWY LEN 900M. RWY 23 WID 12 RWS 15
DTHR 100M.

09/27 20c Unrated. Grass. RWY LEN 600M. WID 24 RWS 30

AERODROME AND APPROACH LIGHTING

RWY 05/23 MIRL PAL 125.3

RWY 05/23 edge LGT spacing: 96M.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA PERTH CENTRE 135.25 On ground

LOCAL TRAFFIC REGULATIONS

1. No flight school training permitted.
2. ACFT should manoeuvre on TWY and RWY only due to soft sand.

FLIGHT PROCEDURES

1. RWY 05 MNM CCT HGT 1,000FT.
2. CCTS not permitted before 0800 on SUN.

CTAF 119.1**ADDITIONAL INFORMATION**

1. Displaced holding point RWY 05 and RWY 09 due overlap.
2. RWY 09/27 grass sprinklers may operate during summer months.
3. Murray Field (YMUL) has identical RWY designators and CTAF.
4. Kangaroo and bird hazard exists.
5. Low level aerobatics in VCY.
6. Emergency Services HEL OPS H24.
7. Refer Perth VTC and VNC.

CHARTS RELATED TO THE AERODROME

WAC 3462.