


SUNRISE DAM

ELEV 1350

AVFAX CODE 6109



WA

290554S

1222719E

UTC +8

VAR 1 DEG E

YSRD

CERT

AD OPR Anglogold Ashanti Australia Ltd - GPO Box F377, Perth, WA, 6001. Email: inflightess@anglogoldashanti.com. PH 08 9080 3765 (BH). ARO 0437 413 119 (H24).

REMARKS
Restricted OPS: PPR from AD OPR.

HANDLING SERVICES AND FACILITIES

JET A1 private installation. Contact National Jet Express, PH 08 8154 7444.
Email: rsgroundops@nje.aero.

PHYSICAL CHARACTERISTICS

06/24	059	64a	PCR 250/F/B/Y/T	WID 30	RWS 150
-------	-----	-----	-----------------	--------	---------

AERODROME AND APPROACH LIGHTING

RWY 06/24	LIRL	PAL 120.25			SDBY PWR AVBL BY PRIOR ARRANGEMENT
RWY 06/24	PAPI	PAL 120.25	3.0 DEG49FT		SDBY PWR AVBL BY PRIOR ARRANGEMENT
RWY 06/24	PTBL(1)				BY PRIOR ARRANGEMENT

- (1) EMERG only. 90MIN PN.
1. RWY edge light spacing: 59M.
2. SDBY PWR is manually activated. 3HR PN for activation.

OTHER LIGHTING

TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	118.4 3,500FT
-----	------------------	---------------

LOCAL TRAFFIC REGULATIONS

RWY 06/24 - RWY end turning nodes - all turns must be MNM speed MAX RAD.

FLIGHT PROCEDURES

ACFT to avoid flying over mine pit.

CTAF - AFRU 126.8

AFRU signal not AVBL on ground Laverton, Murrin Murrin or Sunrise Dam. AFRU located at Leonora.

ADDITIONAL INFORMATION

1. Bird Hazard in VCY of AD (falcons or hawks).
2. Animal hazard (kangaroos). ARO will conduct additional RWY inspection prior to scheduled ACFT OPS.
3. Seasonal wetlands may be present at western end of RWY, ducks, swans and birds of prey maybe in VCY.

CHARTS RELATED TO THE AERODROME

1. WAC 3352.
2. Also refer to AIP Departure and Approach Procedures.