1524036E

YBOA

UNCR

BOONAH

FLEV 330 FULL NOTAM SERVICE NOT AVBL

UTC +10

VAR 11 DEG E



REMARKS

- Landing fee of \$10.00 to all non BAI member aircraft payable in the box on the verandah, 1. Boonah Gliding Club.
- 2. Standard HR for ACFT (other than gliders and circuit training) will be first light to last light.
 - a. No circuit flying before 0700 Local Monday to Saturday and before 0900 Local Sunday.
 - b. No departures RWY 04 before 0700 Local.

HANDLING SERVICES AND FACILITIES

IOR AVGAS - H24 credit card via IOR APP, cash services AVBL via Ultimate Aero Pty Ltd - Contact AD OPR.

PASSENGER FACILITIES

WC/TX 07 5462 4177 or 131 008/ME 0437 767 800.

PHYSICAL CHARACTERISTICS

04/22 Grass, RWY LEN 1.030M. 34c

CTC AD OPR for RWY declared distances.

ATS AND AERODROME COMMUNICATION FACILITIES 119.5 On ground

FIA BRISBANE CENTRE

LOCAL TRAFFIC REGULATIONS

- Carriage and use of radio is required by AD OPR. 1.
- 2. Hump in RWY limits line of sight, radio calls confirming the RWY is in use must be made prior to entering the RWY and landing.
- 3. Tug and glider combination DEP RWY 04 may turn right.

FLIGHT PROCEDURES

- 1. Visiting ACFT not permitted to do straight-in approaches.
- 2. Tug and glider combination DEP RWY 04 may turn right.

CTAF 122.75

NOISE ABATEMENT PROCEDURES

Note: Compliance with the following Noise Abatement Procedures does not affect a pilot's responsibility to operate in accordance with civil aviation legislation and procedures.

- 1. Pilots are requested to avoid the following:
 - a. Low flying over the township and houses.
 - b. Overflying the church located west of RWY 04 (especially before 0900 Local SUN).
- 2. Preferred RWY 22.
- Departures form RWY 04 pilots are requested to maintain RWY heading until past the 3. township.
- 4. Visiting ACFT: touch and go landings not permitted.
- Precautionary search and landing training not permitted. 5.

ADDITIONAL INFORMATION

- Ultralight, gliding and recreational ACFT OPS and training. 1.
- 2. Winch launching and aero-tow for glider OPS.
- 3. Warning: kangaroo hazard exists.
- CAUTION: Use only white midfield WDI for RWY direction, others are spot references. 4.

CHARTS RELATED TO THE AERODROME WAC 3357.