ELEV 869

	FULL NOTAM SERVICE NOT AVE				NOT AVBL	
21	QLD		UTC +10		YESD	
110° 1.0NM	252154S	1510630E	VAR 10 DEG E	-	UNCR	
\\ Eidsvold	AD OPR	North Burnett Regio	nal Council, PO Box 390	, Gayndah,	QLD, 4625.	
	Email: admin@northburnett.qld.gov.au. Council PH 1300 696 272. Fax 07					
\\ 🌩 📩	4161 142	5.				
	REMAR	REMARKS				
	1. No parking on or near areas allocated for EMERG parking.					
	2. Suitable for ACFT up to 5,700KG MTOW.					
32	3. P	PR.				
PASSENGER FACILITIES						
LG/WC.						
AERODROME OBSTACLES						
1. Transition and fly-over OLS infringement exists on both sides of RWS due to trees.						
2. Primary wind indicator infringes the transitional OLS.						
3. COM TWY LOC E of RWY infringes the transitional OLS by 21M.						
PHYSICAL CHARACTERISTICS						
14/32		nrated. Gravel and g ope 0.3% down to N	jrass. RWY LEN 1,189M IW.	. WID 30	RWS 45	
AERODROME AND APPROACH LIGHTING						
RWY 14/32 LIR	L(1)	AFRU+PAL 126.7		SDBY PW	/R AVBL	
(1) EMERG OP	Sonly					
ATS AND AERODROME COMMUNICATION FACILITIES						
FIA BRISBA	NE CENTR	RE	124.1			
CTAF - AFRU 126.7						
ADDITIONAL INFORMATION						
Fly airstrip for wildlife prior to landing.						
CHARTS RELATED TO THE AERODROME						
WAC 3340.						
WAO 3340.						