# MELTON

#### ELEV 670 FULL NOTAM SERVICE NOT AVBL

BY PRIOR

ARRANGEMENT



VIC UTC +10 YMEL 373718S 1443356E VAR 11 DEG E UNCR AD OPR E. Reeve, 995 Coburns Road, Toolern Vale, VIC, 3337. Email: info@meltonairservices.com.au. PH 03 9746 1342. Website: www.meltonairservices.com.au.

REMARKS

PPR - Contact Melton Air Services, PH AD OPR.

HANDLING SERVICES AND FACILITIES

AVGAS AVBL, CTC AD OPR. Cash, V and MC accepted.

PASSENGER FACILITIES

LG/WC/RF/TX/ME.

### PHYSICAL CHARACTERISTICS

04/22	44c	Unrated. Grass/Gravel. RWY LEN 1,340M.	WID 30	RWS 60
		RWY 22 DTHR 90M. Slope 1% down to SW.		
10/28	33c	Unrated. Grass. RWY LEN 1,000M. RWY 28	WID 30	RWS 60
		DTHR 90M. Slope 1% down to SE.		
14/32	39c	Unrated. Grass. RWY LEN 1,200M. Slope 1%	WID 30	RWS 60
		up to N.		
16/34	21c	Unrated. Grass. RWY LEN 650M. Slope 1% up	WID 30	
		to N.		

## **AERODROME AND APPROACH LIGHTING**

RWY 04/22 LIRL

RWY 04/22 edge light spacing: 89M.

## ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE

135.7 Circuit Area

## LOCAL TRAFFIC REGULATIONS

All ACFT DEP (other than touch and go OPS) to commence take off roll from RWY end to maximise height over residential areas after take off.

## FLIGHT PROCEDURES

- 1. Where possible, ACFT should conform to established RWY direction.
- 2. Arrivals at least 3 legs of the circuit to be flown.
- 3. Straight in approaches are not permitted.
- 4. RH Circuits RWY 04 and 10.
- 5. Landings only RWY 34.
- 6. Take off/landing RWY 16 not permitted.
- 7. All ACFT to avoid overflying Toolern Vale township NE of aerodrome.

## CTAF 121.6

## CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.