
TENTERFIELD

ELEV 2624 FULL NOTAM SERVICE NOT AVBL

NSW UTC +10 YTFD 285928S 1515547E VAR 11 DEG E UNCR AD OPR Friends of Tenterfield Aerodrome Association Inc. 321 Timbarra Rd. Tenterfield. NSW. 2372. Email: admin@fota.au. ARO 0428 755 180. Mobile MGR 0418 874 799. Website: www.fota.au.



REMARKS

- 1. Landing Fees:
 - a. Private aircraft below 2,000KG MTOW nil (donation towards maintenance appreciated). b. Other aircraft \$10 per tonne or part thereof MTOW.
 - Parking Fees All aircraft \$5 per day for parking longer than 72 hours.

2. Note: Honesty System - www.fota.au for payment. Use aircraft registration as payment reference.

HANDLING SERVICES AND FACILITIES

JET A1 available for emergency services operations. Call out fee may apply. PH ARO.

PASSENGER FACILITIES

WC.

PHYSICAL CHARACTERISTICS

07/25

Unrated, Grass, RWY undulating with slight rise approx 250M from RWY 25 THR. RWY

LEN 1.270M

AERODROME AND APPROACH LIGHTING

42c

RWY 07/25 PTBL(1)

BY PRIOR ARRANGEMENT

RWS 150

WID 55

EMERG only, 60MIN PN. (1)

RWY 07/25 edge light spacing: 100M.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 126.8 Circuit Area

CTAF 126 7

ADDITIONAL INFORMATION

- RWY soft after heavy rain. 1.
- 2. Bird and animal hazard exists.
- Mower may be on RWY at any time HJ. 3.
- Tenterfield township 10KM south by road. 4

CHARTS RELATED TO THE AERODROME

WAC 3357.