


BARWON FIELD



VIC
380849S
AD OPR Craig Taberner, 470 Pollocksford Rd, Gnarwarre, VIC, 3221. Email: ctaberne@ford.com. PH 0439 154 202 (H24).

1441021E

UTC +10
VAR 12 DEG E

ELEV 260
FULL NOTAM SERVICE NOT AVBL
YGBF
UNCR

REMARKS
PPR.

PHYSICAL CHARACTERISTICS

02/20	28c	Unrated. Grass. RWY LEN 850M	WID 15
15/33	28c	Unrated. Grass. RWY LEN 850M	WID 15

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	134.325
-----	------------------	---------

FLIGHT PROCEDURES

1.

Right hand circuits for RWY 02 and RWY 33.

2.

No landing on RWY 02 due to rising terrain to south.

CTAF 119.0

ADDITIONAL INFORMATION

Pilots should consider noise impacts and avoid overflying residential buildings.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.